Approved For Release 2007/12/04 : CIA-RDP80-00810A005700540003-0

COUNTRY Polland

SULJECT

DATE DISTR

11 Johnson 1:57

2

Masso 'p 1: Secont Pastery in Opole

NU OF PAGES

NO. OF ENCLS.

SUPPLEMENT TO REPORT NO.

PLACE **ACQUIRED** DATE OF INFO.

THIS IS UNEVALUATED INFORMATION

- The Masto Opole Cement factory in Oppeln (Opole) was located on the west side of the Copeln-Klostertrueck (Czarnowasy)-Namslau (Namyslow) (P 52/C 92) road, letween the town of Oppeln and the Sckreu suburt (Zakrzow), atout 300 meters southeast of the hartor, and approximately 1,200 meters west--northwest of the Oppeln stadium. The factory had three spur tracks which joined the tracks of the harlor line outside of the installation. The municipal power station provided the installation with power.
- 2. The installation erea extended approximately 300 x 300 meters excluding the quarry area east of the Oppeln-Klosterbruck road which reasured 500 x 800 25X1
- 3. The instellation was partially damaged during the war and was dismantled by the Soviets after the war. In 1946, the factory was rebuilt and was put in operation in 1947. Reconstruction work, which was done predominantly by Czech engineers and fitters, was still under way in 1954. Almost all machines were imported from Czechoslovakia, 25X1
- 4. The installation was subordinate to the head organization of cement factories in Poland, the Zjednoczenie Fabryk Cementu Rzeczypospolitej Polski at ul. 3-go laja 22 in Sosnowiec. Prior to larch 1954, the installation had a Polish director and manager, who was dismissed because of non-fulfillment of the production plan. He was succeeded by a Gorman who had decided to become Polish.
- 5. The installation employed 600 workers who worked in three shifter except for repair sections. In addition to these workers, an undetermined number of clerks and engineers were employed in the installation. The later force of the quarry numbered approximately 300 men who also worked in three shifts.
- 6. The installation had an average daily output of 300 tons of cement, which was scheduled to be increased to 350 tons. In June 1954, a section for the reduction of typsum was still under construction.
- 7. The bulk of the production was shipped by rail. An average of 16 to 18 railroad, cars, with a supercity of 18 tons each, daily left the installation,

CLASSIFICATION COMPUBLITIAL-U.S.OFFICIALS ONLY							
STATE	X NAVY	I	NSCB		DISTRIBUTION		
ARMY	ZIAIR	X	FBI				
The state of the s							





	CONFIDENTIAL - U.S. OFFICIALS ONLY	05)/4
	. 2	25 X 1
	About 50 percent of the coment was shipped to the USSR, 3 or 4 percent to Oppeln and vicinity and the rest to Warsaw.	
8.	The installation was surrounded by a wall and, in some parts, by a barted- wire fence. The installation was guarded by approximately 50 factory police who were equipped with rifles.	
, 9∘	Six ouffer cement factories were located in the Oppeln area. Two of these factories, namely the former Silesia works and the plant in Neudorf, were still dismantled and damaged and four factories were in operation.	
		25 X 1

CONFIDENTIAL

- U.S. OFFICIALS ONLY